ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0351, W0319, W0347, W0027	S Krishnappa Lyt, 11th Crs Lakshmi Sagar Lyt, R H B Colcny 2nd Main Rd, NA	Singapura circle
Segment No.	**Total Length (m)**	
11/C-W0351/S013703	117.44	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	117.44	77.537526	13.080312	77.538242	13.079528	Signapura circle	Abbigere road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements drain and construction of culverts at Singapura Village cross roads and surrounding area in ward no. 11 (Kuvempunagara) in Vidyaranyapura	2800000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	Existing SSM drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		011-17-000003
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/50/2016-17	04/05/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/06/2017	30/06/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Aswathnarayana		0.00
Phone No.	**E-Mail ID**	
9448034435		

Field Inspection Details

Number of Trees

0

Any Other Information

Name

gurusiddappa c gokhule

Date of Inspection

29/06/2017

Remarks

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	29/06/2017	21/07/2017	Approved
SE	K.M.Vasu	29/06/2017	21/07/2017	Verified
EE	H.T. Mohandas	29/06/2017	21/07/2017	Verified
AEE	Shivakumar m goudar	29/06/2017	21/07/2017	Verified
AE	Gurusiddappa C Gokhale	29/06/2017	21/07/2017	Mobile verification done
AE	Gurusiddappa C Gokhale	29/06/2017	21/07/2017	Forwarded

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0351, W0319, W0347, W0027

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0301, W0190, W0333, W0250, W0319, W0188, W0186, I	Bimel Behind Rd, NA, 11th Crs Lakshmi Sagar Lyt	Singapura circle
Segment No.	**Total Length (m)**	
11/C-W0301/S012704	247.40	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	247.40	77.536133	13.078680	77.537452	13.080331	Singapura Circle	Abigere main road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements drain and construction of culverts at Singapura Village cross roads and surrounding area in ward no. 11 (Kuvempunagara) in Vidyaranyapura	2800000	2016-17
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Others	RCC drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		011-17-000003
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/50/2016-17	04/05/2017	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/06/2017	30/06/2018	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Aswathnarayana		0.00
Phone No.	**E-Mail ID**	
9448034435		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		gurusiddappa c gokhake

Date of Inspection	Remarks
29/06/2017	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment End		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0301, W0190, W0333, W0250,

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Parameshwaraiah	29/06/2017	21/07/2017	Approved
SE	K.M.Vasu	29/06/2017	21/07/2017	Verified
EE	H.T. Mohandas	29/06/2017	21/07/2017	Verified
AEE	Shivakumar m goudar	29/06/2017	21/07/2017	Verified
AE	Gurusiddappa C Gokhale	29/06/2017	21/07/2017	Mobile verification done
AE	Gurusiddappa C Gokhale	29/06/2017	21/07/2017	Forwarded



Zone: YELAHANKA **Ward No:** 11 **Ward Name:** Kuvempu Nagar **Street ID:** W0301, W0190, W0333, W0250,